

PORTSMOUTH FIRE DEPARTMENT

FIRE PREVENTION BUREAU

Garage Ventilation Testing Procedure and Inspector's Checklist

- 1. Inspector to verify prior to beginning :
 - List of all sensors and their exact locations permanently identified, adjacent to the main gas system controller
 - □ Sign at *all* yellow strobes stating not enter the space when flashing at each interior and exterior door to the garage
 - □ A 24 hour number for service of the gas system is posted adjacent to the main gas system controller
 - City mechanical and electrical inspectors have signed off on the generator. Written/email proof is required
 - □ Documentation that all test gas has NIST traceability. No other test gases shall be permitted
 - □ An exhaust fan is constantly running at low speed prior to proceeding to step 2
- 2. Contractor to release 25-50 PPM CO testing gas at sensor(s). Inspector to verify:

□ Louver(s) open and fan(s) speed increase or turn on at <u>25PPM CO (1st stage/set/trip point)</u>

3. Contractor to release 100-140 PPM CO testing gas at sensor(s). Inspector to verify:

□ Louver(s) still open and fan on maximum at <u>100PPM CO (2nd stage/set/trip point)</u> □ Gas strobe circuit of FACP energizes at 100PPM CO and does not silence until CO is below 100 PPM. A selfresetting supervisory condition is generated at the FACP (to allow strobe syncing, the fire alarm must control strobes)

4. Contractor to release 200-250PPM CO testing gas at sensor(s), inspector to verify:

Fire alarm system activation at <u>200 PPM CO (alarm level/point)</u>, fire alarm to sound general evacuation signal, gas alarm transmitted
Fans to run for 15 minute after alarm condition clear (Only for <u>the test</u>: fans shall run for 1 minute after)

5. Contractor to de-energize utility power to the emergency power panelboard and demonstrate to inspector:

 \Box ATS has successfully transfer load to generator, prior to proceeding to step 6.

6. Contractor to return gas system to normal condition, then: Release 1-10PPM NO2 test gas at sensor(s). Inspector to verify: (continued on page 2)

 \Box Louver(s) open and fan(s) speed increase or turn on at <u>0.7 – 1.5PPM NO2 (1st stage/set/trip point)</u> This step is performed under generator power.

7. **Contractor to return gas system to normal condition, then: Release 1-10PPM NO2 test gas at sensor(s). Inspector to verify:

 \Box Louver(s) open and fan(s) on maximum at <u>1.6 – 3.0PPM NO2 (2nd stage/set/trip point)</u>. This step is performed under generator power. (**This step is optional if the controller does not have a 2nd stage/set/trip point for NO2)

8. Contractor to release 5-10PPM NO2 test gas at sensor(s). Inspector to verify:

□ Louver(s) still open and fan(s) on maximum, under generator power

Gas strobe circuit of FACP energizes at <u>5PPM NO2 (alarm level/point)</u>, fire alarm to sound general evacuation signal, gas alarm transmitted

□ Fans to run for 15 minute after 5 PPM NO2 alarm condition clears.... Only for the test: fans shall run for 1 minute after

9. Contractor to re-energize utility power to the emergency power panelboard and, demonstrate to inspector:

□ ATS has successfully transferred load to utility power, prior to proceeding to step 9

10. Contractor to return gas system to normal condition, then place it in trouble, inspector to verify:

□ FACP indicates a trouble condition (fire alarm shall monitor gas system for troubles)

11. Contractor to identify to the inspector a breaker lock is secured to the branch circuit overcurrent protection device and disconnect(s) are locked on for:

□ Gas system controller(s)

□ Fan motor controller(s)

 \Box Louver controller(s)

Inspection shall be coordinated to have the mechanical inspector present, as required. The fire alarm contractor shall be present and the fire alarm shall have been successfully inspected prior. A minimum of 7 days advanced notice is required to schedule this type of inspection, <u>no</u> exceptions. Any deviations from this procedure shall be requested in writing prior to scheduling the inspection.

Any failure shall result in a \$300 re-inspection fee.