

HALL CEMETERY 2025



Front Row before work



Part of a Hall headstone in front row – before applying epoxy.



Front Row after resetting and epoxying. The headstone pieces (shown in previous picture) are part of the 4th headstone from the left.



Three of the Hall children's graves before excavation and repair.



Three of the Hall children's graves after repair and resetting. The 3 footstones were discovered during the work, and repaired before resetting.



Before work on the Shore family headstones. One headstone was discovered under the fallen headstone on the left.



After repair and resetting of the 3 Shore Family members. These still need to be cleaned with D2.