

North and Union Railing

By Portsmouth Historic Cemetery Committee

November 6, 2025

North Cemetery Sheafe Plot

The railing in the backdrop
needs to be lifted and secured
to the post in the foreground.



North Cemetery Walker Plot

The railing is bent. Is it possible to straighten out?



Union Cemetery Missing Spirals

These two images show the top/spiral of the fencing is missing. The top photo shows several missing spirals and some that are bent.

The bottom photo shows two missing spirals.

Can the missing spirals be restored and the bent ones straightened out?



Union Cemetery Unsecured Rail

The top railing in this photo lifts easily but needs to be secured to the cement post.



Union Cemetery Underground Rail

The top railing in this photo is does not fit between posts.
The bottom rail is buried and possibly on the right secured to the bottom when it should be secured to the top.



Union Cemetery Broken Fence

A section of this fence is missing. Parts of the missing fence might be in the foreground but it is shorter than the missing piece. What would be the best approach to restore this?

